



# WARRIOR TECH



## WELDING HELMET USER INSTRUCTIONS

# WARRIOR TECH User Manual

Information manual for the WARRIOR TECH welder protective helmets complying with Par. 14 of Appendix II of the EC regulations. The WARRIOR TECH welding helmets are high quality products that contribute to the comfort and safety of the welder. WARRIOR TECH welding helmets may be used only in connection with arc welding. The chart below shows how to choose the most suitable shade level.

Welding process Or related techniques	Current internally in amperes															
	0.5	2.5	10	20	30	40	60	80	100	125	175	225	275	350	450	
	1	5	15	30	40	60	80	100	150	200	250	300	400	500		
E manual Flux cored electrodes Fluxed stick electrodes								9	10		11		12		13	14
MIG / Metal-Inert Gas Argon (Ar/He) Steels, alloyed steels, Copper & its alloys etc.										10	11		12		13	14
MIG / Metal-Inert Gas Argon (Ar/He) Aluminium, copper, nickel And other alloys.									10	11		12		13	14	15
TIG / Tungsten-Inert Gas Argon (Ar/He) (Ar/He) All weldable metals such as: Steels, aluminium, Copper, nickel and their alloys.						9	10			11		12		13		
MIG / Metal-Inert Gas (Ar/He/CO <sub>2</sub> ) (Ar/CO <sub>2</sub> /He/CO <sub>2</sub> ) Carbon-Steel, low-alloy & temperal steels Cr-Ni-alloys, Cr-steel & other alloyed steels.									10	11	12		13		14	15
Electrode arc compressed air plasma (MIG plasma) carbon electrode (C2) Plasma gas: compressed air (C2)										10	11	12	13	14	15	
Plasma cutting (Plasma cutting) All weldable metals see 1010 Copper and other gas Argon (Ar/He) (Ar/He)										11		12		13		
Plasma cutting (Plasma cutting) Micro-plasma welding Copper and other gas Argon (Ar/He) (Ar/He)	2.5 4	5	6	7	8	9	10	11		12		13		14		15

Depending upon the application conditions, the next highest or next lowest protection level can be used.  
The darker fields correspond to those areas in which the corresponding welding process cannot be used.

## Information

WARRIOR TECH welding helmets afford reliable protection for the eyes whilst electric arc welding. They offer permanent protection against UV/IR rays, heat & sparks in any state from the clear to dark. The protection shades of the WARRIOR TECH welding helmets have been chosen to avoid eye damage caused by the welding arc.

Do not look directly at welding rays with unprotected eyes when the arc strikes. This can cause a painful inflammation of the cornea and irreparable damage to the lens of the eye leading to cataracts.

WARRIOR TECH welding helmets allow the welder to see the point of arc strike more precisely. This leads to a real time saving. The helmet does not have to be flipped up and down during welding, both hands are kept free and because of the helmets light weight fatigue is reduced.

## Range of application:

The WARRIOR TECH welding helmets can be used for the following applications:


- Electrode
- MIG
- Mag
- Tig (p=5A)

They are not suitable for use with laser systems and oxy-acetylene (gas welding) applications. The welding filter must not be used for any other purpose other than welding. They should never be used as sunglasses when driving as this could lead to incorrect identification of the colour of traffic light. The welding filters operate well under extreme low lighting and very strong sunlight.

## Operation

### Adjustment of headgear:


WARRIOR TECH welding helmets are equipped with a comfortable headgear that can be adjusted in three different ways




## Replacing the Outer Spatter Lens:

Ensure that the helmet is always equipped with an Outside Lens (before the filter, on the outside of the helmet) and an Inner Lens (behind the filter, inside the helmet). These protection lenses must be replaced if broken, damaged or covered with welding spatter to such an extent that vision is impaired. Inner & Outer Lenses are consumables and must be replaced regularly with certified ESAB spare parts (CE marked).

Before using the WARRIOR TECH helmet for the first time the protective films must be removed from the Front Spatter Lens (drawing 1). The films cannot be removed from the Front Spatter Lens with the Lens in place. Please follow the instructions below to remove the Spatter Lens.



drawing 1



drawing 2

### Inserting and removing a new protection lens:

To insert the new outer protection lens the filter must be removed by unscrewing the two retaining screws from the inside of the helmet. The old protection lens can then be removed and the new lens inserted followed by the light seal cradle, ADF, inner protection lens and then the ADF retaining frame and finally replace the two retaining screws (see drawing 2).

## Servicing and maintenance

WARRIOR TECH welding helmets should not be dropped. Do not place heavy objects or tools (hammers etc.) on or inside the helmet so as not to damage the electro-optical filter.

Always make sure that the helmet is equipped with an outside and inner lens (in front of the filter on the outside and on the inside behind the filter). These protection lenses must be replaced if damaged in any way (see overleaf). They are consumables and should be checked and replaced regularly.

The filter should be cleaned when changing the protection lenses.

This can be done by any of the following ways:

- Wipe with a clean, dry piece of cloth.
- Clean with a piece of smooth cloth moistened with pure alcohol.
- Clean with a commercial disinfectant
- If used properly the welding filter requires no further maintenance during its lifetime.

If a filter should be replaced on a WARRIOR TECH welding helmet, use exclusively certified products (DIN-CE marks). We recommend the use of ESAB welding filters in all WARRIOR TECH helmets.

The filter itself contains no special or toxic products and can be disposed of in the same way as other electronic devices.


## WARRIOR TECH:

To allow the filter to switch, both sensors on the front of the filter must not be covered. The filter then switches to the dark state when the arc strikes and to the clear state when it stops. The filter switches to the light state when the welding arc stops.

### How to set the shade:


- On the **WARRIOR TECH** set the shade by turning the knob on the outside of the helmet (pos. 1).
- The most suitable setting can be found on the Chart in this brochure or chosen using your experience. This setting can also be made manually during the welding process.

Turning clockwise = darker  
Turning anti clockwise = clearer



### Before using the filter we recommend the following adjustments are made:

- Turn the sensitivity knob clockwise to the max. setting (pos. 2). Depending upon the surrounding light the filter will switch to the dark state or will flicker (if the surrounding light is very low, the filter may not switch to the dark state).
- Turn back the sensitivity knob (pos. 2) until the filter switches to the clear state.
- The filter is now set to its optimum sensitivity (According to the surrounding light conditions).



### Range of use for the WARRIOR TECH

- All arc welding applications with the exception of TIG-c5A and pulse inverter.
- Available shade - 9-13 (pos.1).

### Setting the delay

- The clearing delay can be adjusted manually by turning the delay knob (pos. 3) between a fast clear (0.1 sec) fully anti-clockwise and a slow clear (1.0 sec) fully clockwise.

## Spare parts for WARRIOR TECH Welding Helmets

Items without a part number are not available as spare parts

No.	Part No.	Description
1	0700000400	Warrior Tech 9-13 Black
1	0700000401	Warrior Tech 9-13 Yellow
2	0700000415	Esab Head Gear
3	0700000244	Sweat band for Warrior Tech
4	0700000010	Front cover lens
5	0700000416	Inside cover lens
6	0700000418	Warrior Tech ADF cradle
7		ESAB ADF 9-13
8	0700000419	Warrior Tech Lens retainer with screws

### Filter Testing:

Before use of the welding helmet the auto darkening filter (ADF) and helmet needs to be checked according to the following procedure:

Check outer protection lens is clean and can be seen through.

Ensure the sensors are covered in any way and are clean.

Once these checks have been carried out you can now test the ADF:

Turn the outside shade knob to the darkest setting (shade 13) and set the sensitivity to the highest setting (turning clockwise). Now point the sensor towards a light source such as an overhead light, lamp etc. The ADF should now switch to the dark state (please note if the ADF is stored in a dark area away from light it may need to be left out in strong light for 20 minutes to absorb power, if after 20 minutes if the ADF does still not react then there is an issue with the sensor). Once the filter is in the dark state you can check the shade variation is functioning correctly, simply turn the shade knob anti-clockwise. By doing this, the shade should get lighter. If the shade does not appear to alter then you have an issue with the shade variation.

To test the delay function set the delay to the maximum setting. Now move the filter sensor away from the light source it should take 1 second to return to the light state, now alter the delay setting to the minimum and repeat the process, the time taken to return to the clear state should be 0.1 second. If the ADF does not react in this way then there is an issue with the delay function.

Testing the sensitivity. Set the sensitivity to minimum setting now point the ADF at the light source you used to test the other functions (if filter switches to dark state move away until the filter returns to clear state) slowly turn the sensitivity clockwise until the filter switches to dark state (if it does not then move closer to the light until it reacts). If the ADF does not react then there is an issue with the light sensors.

If any of the functions fail during testing or in use then please do not use the ADF and contact your local distributor.

## Warning

The auto-darkening filters fitted in the WARRIOR TECH helmets are not waterproof and will not work properly if they have been in contact with water. Welding helmets and filters only resist a certain amount of heat. Please do not place them near naked flames or hot work areas etc. Operating temperature of electronic filter minus 10° to plus 65°.  
Materials that may get in contact with the wearers skin could cause Allergic reactions to susceptible individuals

## Certification and Control labels



European Conformity mark.  
This confirms that the product fulfils the requirements of the Directive 89/686/EWG

**ANSI Z87.1**

**AS/NZS**

**CSA Z94.3**

NOTIFIED BODY  
ECS GMBH  
REGISTRATION NUMBER: 181  
ECS GmbH  
Obere Bahnstrasse 74  
73431 Aalen  
Germany

**EN 175:1997**  
**EN 166 B: 2001**

NOTIFIED BODY  
DIN CERTO mbH  
Alboinstr. 56  
D-121103 Berlin  
Germany

## ADF Marking Explanation:

**CE 4/9-13 ESAB 1/2/1/2/379**

4 - Light state scale number  
9 - Lightest dark state scale number  
13 - Darkest state scale number  
ESAB - Manufactures identification  
1 - Optical class  
2 - Diffusion of light class  
1 - Variation in luminous transmittance class  
2 - Angle of dependence classification  
379 - Number of the standard

**ESAB AB**  
**Lindholmsallén 9**  
**Box 8004**  
**402 77 Gothenborg**  
**Sweden**  
**Tel: +46 (0) 31 50 90 00**  
**www.esab.com**

