

# **Product Data Sheet**

**OK Autrod 18.16 / 5183** 

G 'Gas-shielded metal-arc welding'

Signed by	Approved by	Reg no	Cancelling	Reg date	Page
Mats Linde	Mats Öhman/Barbro Karlström	EN002497	EN001133	2004-10-26	1 (2)

### **REASON FOR ISSUE**

Classification and chemical composition modified.

### **GENERAL**

OK Autrod 18.16 was developed to provide the highest strengths possible in the as welded condition of alloy AA 5083 and other similar high magnesium alloys. The more common OK Autrod 18.15 will typically fail to meet the as-welded tensile requirements of AA 5083. The alloy is typically utilised in marine and structural applications where high strengths, high fracture toughness for impact resistance and exposure to corrosive elements are important. The alloy is not recommended for elevated temperature applications due to its susceptibility to stress corrosion cracking. The alloy is non-heat treatable.

Shielding Gas: I1, I3	(EN 439)	Alloy Typ	Alloy Type: AIMgMn				
CLASSIFICATIONS Wire Electrode		APPROV	APPROVALS				
SFA/AWS A5.10	ER5183	Ü	61.039				
EN ISO 18273	S AI 5183	ABS	ER5183				
	(AIMg4,5Mn0,7(A))	BV	WC				
		DB	61.039.03				
		DNV	5183 (WC)				
		GL	RAIMg4.5				
		LR	WC/I-1, RC/I-1				
		UDT	DIN 1732				
		VdTÜV	04666				

## **CHEMICAL COMPOSITION**

## Wire/Strip (%)

	Min	Max
Si		0.25
Mn	0.60	1.00
Cr	0.05	0.25
Cu		0.10
Ti		0.15
Zn		0.25
Fe		0.40
Be		0.0003
Mg	4.3	5.2
Other each		0.05
Others total		0.15
	Comments: Al balance	



# **Product Data Sheet**

**OK Autrod 18.16** 

G 'Gas-shielded metal-arc welding'

Signed by	Approved by	Reg no	Cancelling	Reg date	Page
Mats Linde	Mats Öhman/Barbro Karlström	EN002497	EN001133	2004-10-26	2 (2)

### **MECHANICAL PROPERTIES OF WELD METAL**

### **All Weld Metal**

	As welded		
Properties	Min	Тур	
Rp0.2 (MPa) Rm (MPa) A4-A5 (%)	125 275 17	140 290 25	
Charpy V at 20°C (J/cm2)	20	30	

## **ECONOMICS & CURRENT DATA**

Dimension (mm)	Current (A)		W	η	Н		Feed		U	
Ø	Min	Max	Nom	Nom	Min	Max	Min	Max	Min	Max
0.8	60	170	15						13	24
1.0	90	210	16						15	26
1.2	140	260	19						20	29
1.6	190	350	25						25	30
2.4	280	400	30						26	31

**W** = Gas consumption (I / min)

η = Recovery, g weld metal / 100g wire (%)H = Deposit rate (kg weld metal / hour arc time)

Feed = Feeding rate (m/min)
U = Arc voltage (V)

## **OTHER DATA**

Clean material is essential for a good weld quality. Remove oxide, dirt, oil, humidity etc. before welding. If brushing use a stainless steel wire brush.Preheating: is not required for welds in sections up to 20 mm but risk of porosity can be reduced by preheating sections over 10 mm. Preheating temperature is usually 150-200 °C.